
MARION COUNTY SURVEYOR'S OFFICE

SECTION CORNER RECORD DEBRA S. JENKINS MARION COUNTY SURVEYOR

SEC. 34 TWN. 15_{N} RNG. 3_{E}

BRYAN F. CATLIN, PLS TECHNICAL SUPERVISOR



Corner originally set as a post in 1820 by Wm. B. Laughlin with the following witnesses: 4" buckeye bearing N 26 W 9 links; and a 4" dogwood bearing S 24 E 9 links (Marion County Atlas p. 7). A survey by D.B. Hasbrook on 6/16/1850 indicates no stone, but the following witnesses: 18" B. oak bearing S 58.50 E 21 links; and a 20" B. oak bearing N 88.25 W 42 links (Perry Legal Book p. 13&18). Corner referenced by Prout in 1970 and retied. Corner referenced by Wilcoxen on 2/17/83 and called a found rebar. Corner referenced by Kiste on 7/20/93 and called a PK nail found in the center of a cut x in the concrete. Corner referenced by MCSO on 10/5/1999 and called a broken PK nail in the center of the cut x. Corner referenced by Wilcoxen on 10/1/2004 and called a broken PK nail in the center of the cut x. Corner referenced by Wilcoxen on 10/12/09 and called a broken PK nail in the center of a cut x.

PwP 3.

REF.	DISTANCE	DESCRIPTION
REF.	DISTANCE	DESCRIPTION
1.	65.50'	PK nail W 36" tall cut-off PwP 24" up
2.	39.09'	MAG nail W light pole 36" up
3.	168.50'	PK nail w/shiner E light pole #53-692 A 40" up
4.	148.98'	NE corner of concrete block building (mixing plant)
5.	177.06'	Most North-West corner of concrete block building (mixing plant)
6.	61.33'	Cut 'x' SE tower leg 36" up
7.	107.55'	Cut 'x' SE tower leg 48" up